


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?		
D1028-162	Dye	4/22/2009	ADS/TM	S11UU_009MH	Damp	NA		
Address	3401 Rosedale Road		Location	Curb	Status	Public	Source	Catch Basin



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Run Summary							
Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?	
D1028-162	Dye	4/22/2009	ADS/TM	S11UU_009MH	Damp	NA	
Address	3401 Rosedale Road		Location	Curb	Status	Public	Source Catch Basin

### Observations & Photos

**Obs\_ID** D1028-162-OB01

**Nearest MH** S11UU\_009MH

**Comments** Dye observed 63.5 ft. downstream of S11UU\_009MH. Infiltration runner at joint at 7 oclock.



**Picture** \D1028-162-OB01-P01.jpg

**Comments** 63.5 ft. downstream of S11UU\_009MH along S11UU\_009G1.

---